

## Adhesive Dry Film Holds 3D Shapes



Foam - Wood - Plastic - Fabric - Felt - Metals

## Lay up any of the above for PERFECT 3D PARTS











Auto | Aircraft | Seating | Office | Furniture | Partitions | Cabinets | Signs | Overlay | Backer Fixtures | Musical Instruments | Dieboards | Frame Stock | Packaging





- 1. Heat sandwiched layers flat to 220F.
- 2. Transfer to 3D shaped clamp, mold, or pinch tool.
- 3. Cool into a PERFECT flat or 3D molded component.

## **EXACT QUALITY. EVERY PIECE.**



Office: 616-887-8257 Cell: 616-581-6466 www.lenderink.com